

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 5 M

CATATAN : Beton

LOKASI : STA 0+010

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

CATATAN : Paving

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono			1

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 0+100

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

CATATAN : Paving

LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang


LEBAR PERKERASAN : 3.5 M

CATATAN : Paving

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	2

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngijono



LOKASI : STA 0+300

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

CATATAN : Paving

LOKASI : STA 0+400

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngijono		0	3

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngijono



LOKASI : STA 0+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

LOKASI : STA 0+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngijono		0	4

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 0+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	5

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 0+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

LOKASI : STA 1+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	6

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 1+200

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	7

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 1+300

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 1+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	8

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

LOKASI : STA 1+600

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	9

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 1+700

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

LOKASI : STA 1+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	10

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 1+900

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal



LOKASI : STA 2+000

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	11

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 2+100

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal



LOKASI : STA 2+200

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	12

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 2+300

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 2+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	13

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 2+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 2+600

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	14

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 2+700

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 2+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	15

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 2+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 3+000

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	16

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 3+100

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 3+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	17

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 3+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 3+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	18

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 3+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	19

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 3+800

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	20

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 3+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 4+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	21


FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 4+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 4+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	22

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 4+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 4+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	23

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 4+500

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 4+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	24

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 4+700

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 4+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	25

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 4+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 5+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	26


FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 5+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Beton



LOKASI : STA 5+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	27

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 5+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal



LOKASI : STA 5+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	28

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 5+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
CATATAN : Aspal



LOKASI : STA 5+600

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	29

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 5+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
CATATAN : Beton



LOKASI : STA 5+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	30

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 5+900

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
CATATAN : Aspal



LOKASI : STA 6+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	31


FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 6+100

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 6+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	32

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 6+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 6+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	33

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 6+500

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 6+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	34

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 6+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
CATATAN : Aspal



LOKASI : STA 6+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
CATATAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	35

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 6+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Kerikil



LOKASI : STA 7+000

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	36

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 7+100

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Kerikil



LOKASI : STA 7+200

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	37

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 7+300

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2 M
CATATAN : Kerikil



LOKASI : STA 7+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2 M
CATATAN : Kerikil

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	38

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA 7+490

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2 M
CATATAN : Kerikil



LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
CATATAN :

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	39

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : Bogem - Sumberrejo - Ngiyono



LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
CATATAN :

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
CATATAN :

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
20	Bogem - Sumberrejo - Ngiyono		0	40