

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			1

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO		0	2

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			3

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			4

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			5

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 1+100

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			6

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+200

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 1+300

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			7

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+400

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			8

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+600

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 1+700

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			9

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+800

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal



LOKASI : STA 1+900

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			10

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+000

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 2+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			11

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 2+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			12

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 2+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			13

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+600

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 2+700

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			14

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 2+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			15

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 3+100

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			16

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+200

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 3+300

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			17

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+400

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			18

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+600

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal



LOKASI : STA 3+700

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			19

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal




LOKASI : STA 3+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			20

FOTO SURVEY KONDISI JALAN TAHUN 2023

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : **STA** **3+990**

LOKASI : **STA**

KONDISI PERKERASAN : Sedang

KONDISI PERKERASAN :

LEBAR PERKERASAN : 3 M

LEBAR PERKERASAN : M

CATATAN : Aspal

CATATAN :

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN BLORA	PETUGAS SURVEY	HALAMAN
85	KENDILAN - JENU - SAMBONGREJO			21