

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3 M  
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :            **STA**            **0+400**

KONDISI PERKERASAN :            Sedang  
LEBAR PERKERASAN :            2,5            M  
CATATAN :            Aspal

LOKASI :            **STA**            **0+480**

KONDISI PERKERASAN :            Sedang  
LEBAR PERKERASAN :            3            M  
CATATAN :            Paving

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :            **STA**            **0+500**

KONDISI PERKERASAN :            Sedang  
LEBAR PERKERASAN :            3            M  
CATATAN :            Paving

LOKASI :            **STA**            **0+600**

KONDISI PERKERASAN :            Sedang  
LEBAR PERKERASAN :            3            M  
CATATAN :            Paving

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+700

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3 M  
CATATAN : Paving



LOKASI : STA 0+800

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3 M  
CATATAN : Paving

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

LOKASI : STA 0+900

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

LOKASI : STA 1+100

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 1+300

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 1+400

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 1+500

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 8       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :                **STA**                **1+600**

KONDISI PERKERASAN                :                **Sedang**

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal



LOKASI :                **STA**                **1+700**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 9       |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :                **STA**                **1+800**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal



LOKASI :                **STA**                **1+900**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 10      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : aspal



LOKASI : STA 2+100

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 11      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+200

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 2+300

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 12      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :                **STA                2+400**

KONDISI PERKERASAN                :                Rusak Ringan

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal



LOKASI :                **STA                2+500**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 13      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI :                **STA                2+600**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal



LOKASI :                **STA                2+700**

KONDISI PERKERASAN                :                Rusak Berat

LEBAR PERKERASAN                :                2,5                M

CATATAN                :                Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 14      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 2+800

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 2+900

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 15      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 3+100

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 16      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+200

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 3+300

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 17      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+400

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 18      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+600

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal



LOKASI : STA 3+700

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 19      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+800

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal




LOKASI : STA 3+900

KONDISI PERKERASAN : Rusak Berat  
LEBAR PERKERASAN : 2,5 M  
CATATAN : Aspal

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 20      |

## FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDILAN - JENU - SAMBONGREJO



LOKASI : STA 3+990

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA

KONDISI PERKERASAN : M

LEBAR PERKERASAN : M

CATATAN :

| NO. RUAS | NAMA RUAS                     | DPUPR KABUPATEN BLORA | PETUGAS SURVEY | HALAMAN |
|----------|-------------------------------|-----------------------|----------------|---------|
| 85       | KENDILAN - JENU - SAMBONGREJO |                       |                | 21      |